

Sample Report

Company	PYRA InfraEngiTech Services India Pvt. Ltd. Sahakar Nager 2 pune	Tester: Mr. Ganesh Pimple Phone: 09822199200/08605014987 E-Mail: gpimple@pyra.co.in
----------------	---	---

Device	testo 875-2	Serial No.: 2130200
---------------	-------------	---------------------

Customer	Schindler India Pvt.Ltd Chakan midc Phase II Pune	Measuring Site: Mr. Amol Shirguppe Chakan midc Phase II Pune Measuring Date: 1/11/2014
-----------------	---	---

Task	Paint Both Gate Leakage Checking
-------------	----------------------------------



Sample Report

Sample Report

File:
IV_00160.BMT

Date:
1/11/2014

Measuring Time:
4:00:39 PM




Picture parameters:

Emissivity: 0.95
Refl. temp. [°C]: 20.0


Picture markings:

Measurement Objects	Temp. [°C]	Emiss.	Refl. temp. [°C]	Remarks
Measure point 1	96.6	0.95	20.0	-
Measure point 2	97.6	0.95	20.0	-

Histogram:



Profile line:



Remarks:

Paint Both Furnace Gate, temperature leakage. It is very hazards, kindly check gas kit & gate nut bolts.

Review:

Sample Report

1/14/2014 ,

Mr. Ganesh Pimple